

**SECRET**

OUT56014

1

1965 JUN 22 00 48 Z

**SECRET 220008z**

25X1

1. CAMERA B 122 WAS USED IN MISSION 8024 FLOWN ON 17 JUNE 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

22 JUN 1965

B. 9R SIDE: THERE IS A CREASE ALONG THE OUTBOARD EDGE OF THE FILM ON FRAMES 1021 THROUGH 1026. IRREGULAR, SHORT PLUS DENSITY STREAKS ARE NOTED NEAR THE INBOARD EDGE OF THE FILM ON FRAMES 1304 THROUGH 1311 AND 2046 THROUGH 2048. FINE PLUS DENSITY STREAKS PARALLEL TO AND AT VARIOUS DISTANCES FROM THE FILM EDGES, OCCUR INTERMITTENTLY THROUGHOUT THE MISSION. SMALL AREAS OF FOG ARE PRESENT ON FRAMES 1225, 1443, 1446 AND 1447. THESE FOGGED AREAS PROTRUDE APPROXIMATELY 2.0" INTO THE FILM FROM THE OUTBOARD EDGE. HEAT SPLICES ARE MADE BETWEEN FRAMES 1018/1019, 1026/1027, 1357/1358, 1366/1367, 1928/1929, 2435/2436 AND IN FRAME 1351. A MANUFACTURER'S SPLICE IS MADE IN FRAME 1833. EXCESS PIGMENTS IN TITLING OF FRAMES 1358 THROUGH 1440 ALTERED THE FRAME NUMBERS TO AN EXTENT THAT MADE THEM DIFFICULT TO INTERPRET CORRECTLY. THE DIGITS 3, 8 AND 9 WERE PARTICULARLY AFFECTED.

COPIES RECEIVED		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3, 4	TID	✓
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

C. 9L SIDE: A ROW OF MINUS DENSITY DOTS SPACED 1.70"

APART OCCURS 1.55" FROM THE OUTBOARD EDGE OF THE FILM ON THE FIRST 66 FRAMES. FAINT, INTERMITTENT PRESSURE ROLLER CHATTER IS PRESENT ALONG THE OUTBOARD EDGE OF THE FILM FROM FRAME 481 THROUGH THE END OF THE MISSION. NUMEROUS, SHORT IRREGULAR PLUS DENSITY STREAKS

Declassification Review by NGA/DoD

25X1

**SECRET**

-2-

ARE PRESENT NEAR THE INBOARD ~~EDGE~~ OF THE FILM ON FRAMES 2641 THROUGH 2717. A FEW RANDOM PLUS DENSITY STREAKS ARE NOTED ON FRAMES 1201 THROUGH 1440. A FINE, CONTINUOUS PLUS DENSITY STREAK 0.20" FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT ON FRAMES 1441 THROUGH 1680. ANOTHER FINE, CONTINUOUS PLUS DENSITY STREAK 0.10" FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT ON FRAMES 2161 THROUGH 2400. A MANUFACTURER'S SPLICE IS MADE IN FRAME 179.

D. BOTH SIDES: STATIC DISCHARGES ALONG BOTH FILM EDGES OCCUR INTERMITTENTLY THROUGHOUT. FRAMES ARE TITLED CONSECUTIVELY FROM 0001 THROUGH 2717.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THE MISSION.

3. POSITIVE:

A. FI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 30 PERCENT OF THE MISSION.

S E C R E T

~~SECRET~~

---END OF MESSAGE---